
NOTES:

THIS DWG. REPRESENTS A SUB-GROUP OF COMPONENTS WITHIN THE NG9 COOLING SYSTEM BILL OF MATERIAL AND DOES NOT NECESSARILY REPRESENT THE ACTUAL ASSEMBLY PROCEDURE. THIS DWG DOES PROVIDE TECHNICAL INFORMATION REGARDING COMPONENT LOCATION, SUGGESTED HOSE ROUTING, AND FASTNER APPLICATION.
USE TEFLON PIPE THREAD SEALANT ON ALL TAPERED PIPE THREAD FITTINGS, DO NOT USE TEFLON TAPE.

REV. ECN NO. ZONE DATE APPROVED DESCRIPTION 1 0174 RELEASED FOR PRODUCTION 2 0223 COOLANT PUMP REPLACED WITH NEW BRAND, ITEM 11 WAS 5/8" HOSE. 3/16/2015 RSK 3 0458 HEAT EXCHANGER ZINC LOCATION CHANGE 9/29/2016

10847-SP

3 1 OF 1



4

3