

SEAKEEPER 3 GYRO BOLT-IN CLEARANCES

- 1. REMINDER ! See Bolt-In Installation drawing 90374. WARNING! NEW, SEAKEEPER SUPPLIED BOLTS MUST BE USED FOR EACH INSTALLATION AND REINSTALLATION. IT IS IMPERATIVE THAT TORQUE AND THREADLOCKER GUIDELINES BE FOLLOWED.
- 2. Tight clearances from cable guide bands to hull structure. See below figure for dimensions and reference Seakeeper drawing 90374 for complete gyro envelope.

